

SAFETY DATA SHEET

Section 1: Product and Company Identification

Product Identifier: ER80S-B2 and ER90S-B3 Welding Rod
Product Use: Solid welding wire for GTAW/TIG welding

Item Code:ERSB2- / ERSB3-Supplier Name:PowerWeld Inc.Supplier Address:2501 Beech Street

Valparaiso, IN 46383

Supplier Web Address: www.powerweldinc.com

Supplier Phone: 219-462-8700

1-800-826-9073

Emergency Phone: CHEMTREC (24 hour) 1-800-424-9300

Prepared By: PowerWeld Inc.
Preparation Date: 7 June 2016

Section 2: Hazard Identification

Classification: Not classified Label Elements: Not applicable

Other Hazards: Arc rays can injure eyes and burn skin. Welding arc and sparks can ignite

combustibles and flammable materials. Overexposure to welding fumes and

gases can be hazardous.

Section 3: Composition/Information on Hazardous Ingredients

HAZARDOUS INGREDIENTS	CAS NUMBER	APPROXIMATE CONCENTRATION (%)
Silicon (Si)	7440-21-3	0.1 - 1.0
Manganese (Mn)	7439-96-5	0.5 – 3.0
Copper (Cu)	7440-50-8	0.1 - 1.0
Chromium (Cr)	7440-47-3	1.0 - 3.0
Molybdenum (Mo)	7439-98-7	0.5 – 2.0
Iron (Fe)	7439-89-6	94 – 99

PLEASE NOTE: Hazard only appears as fume

Section 4: First-aid Measures

Inhalation: Inhalation may be the most common cause of overexposure due to the

welding fumes. Large amounts of welding fumes will cause irritation of the nose, eyes and skin. Move from the area that has any fumes to fresh air. If breathing is difficult, give oxygen. If not breathing, give artificial respiration

and transport to nearest medical facility for additional treatment.

Ingestion: Not an expected route of exposure. Rinse month completely and drink a cup

of water if conscious; obtain medical assistance when needed.

Eye Contact: If arc flash or burns occur, obtain medical assistance. Large exposure to

welding fumes may cause irritation to the eyes. Immediately flush upper and lower eyelids with plenty of water. After initial flushing, remove any contact lenses and continue flushing for at least 15 minutes. Rest eyes for 30 minutes. If redness, burning, blurred vision or swelling persists, visit

nearest medical facility for additional treatment.

Skin Contact: Large exposure to welding fumes may cause irritation to skin. If burns

occur, flush with clean cool water for 15 minutes; obtain medical assistance

when needed.

Symptoms: Treat symptomatically; symptoms may be delayed. Show this SDS to the

attending physician.

NOTE: In all severe cases, contact physician immediately. Local telephone operators can provide number of regional poison control centre.

Section 5: Fire-fighting Measures

Flammable: Not flammable; emits toxic fumes when heated

Means of Extinction: Use extinguishing method most appropriate for surrounding fire (water

spray, alcohol-resistant foam, dry chemical or carbon dioxide); do not use water on molten metal. Large fires may be flooded with water from a

distance.

Not available

Auto-ignition Temperature:

Explosion Data Sensitivity to

Mechanical Impact: Not available

Explosion Data Sensitivity to

Static Discharge: Not available Special Equipment: See below

Precautions for Fire Fighters: In the event of fire, wear self-contained breathing apparatus and full

protective gear.

Section 6: Accidental Release Measures

Protective Equipment: See Section 8

Emergency Procedures: This product is in rod form and has no hazards as shipped.

Leak or Spill Procedure: If spilled, the product may be picked up and placed back into the container.

If metals become molten, contain with sand and allow to return back into a

solid for recycle as scrap.

Section 7: Handling and Storage

Handling Procedures and Equipment: Avoid contact with eyes. Avoid breathing dust. Avoid prolonged or repeated

contact with skin. Keep container closed. Use only with adequate ventilation. Wash thoroughly after handling. Avoid contact of spilled

material and runoff with soil and surface waterways.

Storage Requirements: Store in a cool, dry and low humid location. Keep away from heat and open

flame. Ground container and receiving equipment.

Incompatibilities: Strong acids and bases.

Section 8: Exposure Controls/Personal Protection

Exposure Limits:

HAZARDOUS INGREDIENTS	CAS NUMBER	OSHA PEL (mg/m³)	ACGIH TLV (mg/m ³)
Silicon (Si)	7440-21-3	15(dust), 5 (resp)	10(dust), 5(resp)
Manganese (Mn)	7439-96-5	5	0.2(resp), 0.1(inhal)
Copper (Cu)	7440-50-8	0.1(fume), 1(dust)	0.2(fume), 1(dust)
Chromium (Cr)	7440-47-3	0.5	0.5

Molybdenum (Mo)	7439-98-7	15	10(inhal), 3(resp)
Iron (Fe)	7439-89-6	_	

Engineering Controls: Ensure proper ventilation and respiratory protection is used when welding,

brazing or processing. Respiratory protection is recommended and information may be found regarding the OSHA STANDARDS (29 CRF 1910.134), as well as CSA Standards Z94.4, along with many other safety

standards.

Personal Protective Equipment: Respiratory: Use NIOSH approved respirator if exposure limits are

exceeded or where dust exposures are excessive. Consider the potential for exposure to components of the coatings or base material being ground in selecting proper respiratory protection. Refer to OSHA's specific standards for where appropriate. Selection of respiratory protection depends on the contaminant type, form and concentration. Select and use respirators in accordance with OSHA 1910.134 and good industrial hygiene practice.

Hands: Cloth or leather gloves are recommended.

<u>Eyes</u>: Wear helmet or face shield with filter lens of appropriate shade number. See *ANSI/ASC Z49.1 Section 4.2*. Provide protective screens and flash goggles, if necessary, to shield others.

<u>Skin</u>: Approved protection (ie./ welders gloves, apron, sleeves, jacket, etc.) should be worn to prevent injury from sparks and contamination of clothing.

Section 9: Physical and Chemical Properties

Physical State: Solid

Odor and Appearance: Odorless metallic rod

Odor Threshold (ppm): Not available pH: Not available Melting Point: 1600°C (2900°F) Freezing Point: Not available **Boiling Point:** Not available Not available *Flashpoint: Upper Flammable Limit (% by volume):* Not available *Lower Flammable Limit (% by volume):* Not available

Section 10: Stability and Reactivity

Chemical Stability: Stable under normal conditions

Possible Hazardous Reactions: Not available

Conditions to Avoid: Avoid contact with incompatible materials

Materials to Avoid (Incompatibilities): Acids, bases and oxidizing agents

Conditions of Reactivity: Not available

Hazardous Decomposition By-Products:

Welding fumes and gases cannot be classified simply. The composition and quantity of both are dependent upon the metal being welded, the process, procedure and welding consumables used. Other conditions which also influence the composition and quantity of the fumes and gases to which workers may be exposed include: coating on the metal being welded (i.e. paint, painting, galvanizing), the number of welders, the volume of the work area, the quality and the amount of ventilation, the position of the welders head with respect to the fume plume, as well as the presence of contaminants in the atmosphere (such as chlorinated hydrocarbon vapors from the cleaning and degreasing activities).

When an electrode is consumed, the fume and gas decomposition products generated are different in percent and form from the ingredients listed in Section 3. Fume and gas decomposition, and not the ingredients in the electrode, are important. The concentration of a given fume or gas component may decrease or increase by many times the original concentration. Also, new compounds not in the electrodes may form.

Decomposition products of normal operation include those originating from the volatilization, reaction or oxidation of the materials shown in Section3, plus those from the base metal coating, etc., as noted above.

Reasonable expected fume constituents of this product would include: Complex oxides of iron, manganese, silicon, chromium, molybdenum, copper, carbon dioxide, carbon monoxide, ozone and nitrogen oxides. Present OSHA exposure limit for hexavalent chromium, nickel and or manganese may be reached before limit of 5 mg/m3 of general welding fumes is reached.

Gaseous reaction products may include carbon monoxide and carbon dioxide, ozone and nitrogen oxides may be formed by the radiation from the arc in addition to shielding gas like argon and helium when employed. Determine the composition and quantity of fumes and gases to which workers are exposed by taking an air sample from inside the welder's helmet if worn or in the worker's breathing zone. Improve ventilation if exposures are not below limits.

See ANSI/AWS F1.1, F1.3 and F1.5, available from the American Welding Society, 550 N.W. LeJeune Road, Miami, FL 33126. See AWS publications: "Fumes & gases in the welding environment" & "Effects of welding on health"

Hazardous Polymerization:

Will not occur

Section 11: Toxicological Information

Skin Contact: Arc rays can burn skin; skin cancer has been reported

Skin Absorption: Not applicable

Eye Contact: Arc rays can injure eyes

Inhalation: Inhalation is the most likely route of exposure; refer to Effects of Acute

Exposure and Effects of Chronic Exposure below

Ingestion: Unlikely due to form of product; harmful if swallowed

Effects of Acute Exposure: Overexposure or inhalation of large amounts of welding fumes may cause

symptoms such as metal fume fever, dizziness, nausea, dryness and

irritation of your nose, throat or eyes as well as lung disease.

Effects of Chronic Exposure: Overexposure or prolonged inhalation of large amounts of welding fumes

with chromium compounds may cause cancer. Other overexposure or prolonged inhalation of large amounts of welding fumes symptoms may include damage to the central nervous system, respiratory system, skin and

could affect organs such as pancreas and liver.

Irritancy of Product: Data not available

Sensitization to Product: May cause an allergic skin reaction

Carcinogenicity: Nickel and Chromium, and their compounds, are on the list of International

Agency for Research on Cancer as Carcinogenic

Reproductive Effects:Data not availableRespiratory Sensitization:Data not availableToxicological Data:Not available

Aquatic and Terrestrial Toxicity:Data not availablePersistence and Degradability:Data not availableBio accumulative Potential:Data not availableSoil Mobility:Data not available

Section 13: Disposal Considerations

NOTE: Always dispose of waste in accordance with local, provincial and federal regulations.

Safe Handling: Wash with soap and water after handling discarded material.

Methods of Disposal: Prevent waste from contaminating surrounding environment. Discard any

product residue, disposable container or liner in environmentally acceptable manner and in full compliance with any applicable regulations.

Use recycling procedures if available.

Section 14: Transportation Information

This material is not considered as a dangerous good per transportation regulations.

Section 15: Regulatory Information

Canadian Controlled Products

Regulations: This product has been classified according to the hazard criteria of the CPR,

Section 33, and this SDS contains all required information.

U.S. California Proposition 65: This product contains or produces a chemical(s) known to the State of

California to cause cancer and/or birth defects or other reproductive harm.

U.S. Massachusetts - Right to Know

List: Chromium, Copper, Manganese, Molybdenum, Silicon

U.S. Minnesota – Hazardous Substance

List: Chromium, Copper, Manganese, Molybdenum, Silicon

U.S. New Jersey - Right to Know

Hazardous Substance List: Chromium, Copper, Manganese, Molybdenum, Silicon

U.S. Pennsylvania - Right to Know

List: Chromium, Copper, Manganese, Molybdenum, Silicon

Section 16: Other Information

Preparation Date: 7 June 2016
Date of Last Revision: 7 June 2016

This SDS format is in accordance with GHS. PowerWeld Inc. provides the information contained herein in good faith but makes no representation as to its comprehensiveness or accuracy. This document is intended only as a guide to the appropriate precautionary handling of the material by a properly trained person using this product. Product use and conditions of use are beyond the control of PowerWeld. Warranty of materials is limited to test results of product performance as detailed in certificates of compliance. Interpretation of test results is the responsibility of enduser. No other warranties, expressed or implied, are made.